

F-1: Bradford Island Photo Log

Photos taken on May 22, 2003



Bradford Island – photo taken from levee road looking landward (southeast) near Station 160+00 (end of Site 2).



Bradford Island – photo taken from levee road looking south near Station 160+00 (end of Site 2).



Bradford Island – photo taken from levee road west near Station 160+00 (end of Site 2).



Bradford Island – photo taken from waterside of levee looking west, near Station 160+00 (end of Site 2).



Bradford Island – photo taken from landward side levee toe, near Station 110+00 (middle of Site 2), looking south.



Bradford Island – photo taken from landward side levee toe, near Station 110+00 (middle of Site 2), looking west toward Himalayan blackberry (*Rubus discolor*) and willow (*Salix* spp.) thicket.



Bradford Island – photo taken from landward side looking up at levee, toward *Arundo donax* patch on waterside of levee (Station 110+00).



Bradford Island – photo taken from levee road looking south at waterside of levee, near Station 110+00 (middle of Site 2).



Bradford Island – photos taken near Station 70+00 (divides Site 1 and 2), from levee road looking southwest at pumping station, mature sycamore and Fremont cottonwood.



Bradford Island – photos taken just north of Station 70+00 (divides Site 1 and 2), looking north along levee road.



Bradford Island – looking south from levee road at Station 40+00 (middle of Site 1).



Bradford Island – looking west from levee road at Station 40+00 (middle of Site 1).



Bradford Island – looking north from levee road at Station 40+00 (middle of Site 1).



Bradford Island – beaver activity on waterside of levee, near Station 40+00.



Bradford Island – looking southwest from levee road near Station 30+00.



Bradford Island – looking west from levee road near Station 30+00.



Bradford Island – looking northwest from levee road near Station 30+00.